
## BUILDING SAFETY CERTIFICATE

No.



It is certified that the existing building Mallikarjun School.(name of the building or premises) at Bohrakoon, Bhimtal, Nainital (address) is having block (s)floor(s) as per details below.

in School	(1)	Block	Block	Block	Block	Block
No. of Floor(s) in the Block	Floors (2) Wings (1)	Floors (2) Wings (1)	(3)	(4)	(5)	(6)

The Building is owned/occupied by Mallikarjun School (Name of the Institution) have complied With the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (Name of Department /Govt.) on 16.04.2024 (date of inspection) in the presence of Mr. Kamal Chance (name and addresses of the Manager/Secretary or his representative) and that the building /premises is fit for occupancy for running school with effect from 14.04. 2024 for a period of Two years in accordance with rule and subject to compliance of the specific condition as appended.

- 1. 2. 3.
- 4.

Issued on 17.04. 2024 at Nainital by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet

Signature:

Name: Mohan Tiwari

15m1 1612124

ATT AND ANY TO P

Designation: Exe Cutive Engineer Name & Address of Department/Office:

P.W.D 15+11 16/04/2024 thi 35101 filling आहायता के साम विद्यालय का निरीस्व किया गया, विद्यालय स्तत्म से साम्बाद्यत स्वजी यताकेन मिरीयन करने के उपगत विद्यालय झवन संरचनात्मक रूप में सुरक्ति पाया गया

रूक ल अवन का निरीक्षण कर स्पष्ट आरूम।

EML 161412 RETTY PORTA

भाग गराइ लो ति हि PLA STOTIS 2

the DP-M

MALLIKARJUN SCHOOL

BHIMTAL (NAINITAL)

Mallikarjun School Chairperson